



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION

01 STATE 02 SITE NUMBER
ILD1005938790

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site) Bosch Trucking Firm		02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER 5600 So. Washington			
03 CITY Bartonville	04 STATE IL	05 ZIP CODE 61607	06 COUNTY Peoria	07 COUNTY CODE 143	08 CONG DIST 18
09 COORDINATES LATITUDE 40 55 30.0		LONGITUDE 089 51 10.0		Peoria West 7.5 Quad (108B)	
10 DIRECTIONS TO SITE (Starting from nearest public road)					

III. RESPONSIBLE PARTIES

01 OWNER (If known) Bosch Trucking Firm		02 STREET (Business, mailing, residential) 5600 S. Washington			
03 CITY Bartonville	04 STATE IL	05 ZIP CODE 61607	06 TELEPHONE NUMBER ()		
07 OPERATOR (If known and different from owner)		08 STREET (Business, mailing, residential)			
09 CITY	10 STATE	11 ZIP CODE	12 TELEPHONE NUMBER ()		
13 TYPE OF OWNERSHIP (Check one) <input checked="" type="checkbox"/> A. PRIVATE <input type="checkbox"/> B. FEDERAL: _____ (Agency name) <input type="checkbox"/> C. STATE <input type="checkbox"/> D. COUNTY <input type="checkbox"/> E. MUNICIPAL <input type="checkbox"/> F. OTHER: _____ (Specify) <input type="checkbox"/> G. UNKNOWN					

14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)

☐ A. RCRA 3001 DATE RECEIVED: ____/____/____ MONTH DAY YEAR ☐ B. UNCONTROLLED WASTE SITE (RCRA 103 d) DATE RECEIVED: ____/____/____ MONTH DAY YEAR ☒ C. NONE

IV. CHARACTERIZATION OF POTENTIAL HAZARD

01 ON SITE INSPECTION <input checked="" type="checkbox"/> YES DATE 06/12/80 MONTH DAY YEAR <input type="checkbox"/> NO Complaint		02 BY (Check all that apply) <input type="checkbox"/> A. EPA <input type="checkbox"/> B. EPA CONTRACTOR <input checked="" type="checkbox"/> C. STATE <input type="checkbox"/> D. OTHER CONTRACTOR <input type="checkbox"/> E. LOCAL HEALTH OFFICIAL <input type="checkbox"/> F. OTHER: _____ (Specify) CONTRACTOR NAME(S): _____			
03 SITE STATUS (Check one) <input type="checkbox"/> A. ACTIVE <input type="checkbox"/> B. INACTIVE <input checked="" type="checkbox"/> C. UNKNOWN		04 YEARS OF OPERATION BEGINNING YEAR _____ ENDING YEAR _____ <input checked="" type="checkbox"/> UNKNOWN			

04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED

facility located over ~~old~~ "Steel slag" landfill

05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION

groundwater (population)

V. PRIORITY ASSESSMENT

01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, complete Part 2 - Waste Information and Part 3 - Description of Hazardous Conditions and Incidents)			
<input type="checkbox"/> A. HIGH (Inspection required promptly)	<input checked="" type="checkbox"/> B. MEDIUM (Inspection required)	<input type="checkbox"/> C. LOW (Inspect on time available basis)	<input type="checkbox"/> D. NONE (No further action needed, complete current disposition form)

VI. INFORMATION AVAILABLE FROM


01 CONTACT Steve Wright	02 OF (Agency/Organization) Bosch Trucking Firm	03 TELEPHONE NUMBER ()
04 PERSON RESPONSIBLE FOR ASSESSMENT Kenneth L. Page	05 AGENCY IEPA	06 ORGANIZATION RPMS
07 TELEPHONE NUMBER 217 7826760		08 DATE 4/10/86 MONTH DAY YEAR

EPA FORM 2070-12 (7-81)

EPA Region 5 Records Ctr.



296358



I HIGHLY VOLATILE
J EXPLOSIVE
K REACTIVE
L INCOMPATIBLE
M NOT APPLICABLE

EPA FORM 2070-12 (7-81)



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

1. IDENTIFICATION

01 STATE 02 SITE NUMBER

ILL 005938790

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 ☒ A GROUNDWATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED

6/10

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

☐ ALLEGED

old landfill used to dispose of steel "slag", potential percolation of substances into groundwater.

01 ☐ B SURFACE WATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

01 ☐ C CONTAMINATION OF AIR

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

01 ☐ D FIRE/EXPLOSIVE CONDITIONS

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

01 ☐ E DIRECT CONTACT

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

01 ☒ F CONTAMINATION OF SOIL

03 AREA POTENTIALLY AFFECTED: 0 (ACRES)

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☒ POTENTIAL

☐ ALLEGED

~~At this~~ facility is located over an old steel "slag" landfill.

01 ☐ G DRINKING WATER CONTAMINATION

03 POPULATION POTENTIALLY AFFECTED

6/10

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

"A" above

01 ☐ H WORKER EXPOSURE/INJURY

03 WORKERS POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED

01 ☐ I POPULATION EXPOSURE/INJURY

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE _____)

04 NARRATIVE DESCRIPTION

☐ POTENTIAL

☐ ALLEGED



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER
TLD 005938790

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☐ J. DAMAGE TO FLORA
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ K. DAMAGE TO FAUNA
04 NARRATIVE DESCRIPTION (include name(s) of species)

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ L. CONTAMINATION OF FOOD CHAIN
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ M. UNSTABLE CONTAINMENT OF WASTES
(Spills, runoff, standing liquids, leaking drums)
03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

04 NARRATIVE DESCRIPTION

01 ☐ N. DAMAGE TO OFFSITE PROPERTY
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☒ P. ILLEGAL/UNAUTHORIZED DUMPING
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☒ POTENTIAL

☐ ALLEGED

Alleged that facility is located over an old landfill that was
use to dispose of steel "slag"

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

III. TOTAL POPULATION POTENTIALLY AFFECTED: 6,110

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references, e. g., state files, sample analysis, reports)

IEPA Division File - LAND

EXECUTIVE SUMMARY

Bosch Trucking Firm, ILD005938790, is a trucking depot located at 5600 South Washington in the Village of Bartonville, Illinois.

On June 8, 1980, a complaint was filed with this Agency that the trucking depot is located over an old landfill, and seven of the employees have cancer. On June 12, 1980, the complaint was investigated and found that the facility is located over an area once used by Keystone to get rid of steel "slag". Mr. Steve Wright, Manager, was aware that five people who had worked for the company had died of cancer.

This site should be further investigated with the cooperation of the County Health Department to assess the danger, if any, that the old landfill is having on humans. A medium priority is assigned.

KP:tk:4/10/16(4/14/86)

